

Inspection Photos
Location Name: TIERA 11-21
API #: 05-071-09073
INSP. #:695100640



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: TIERA 11-21
API #: 05-071-09073
INSP. #:695100640



**PHOTO 3: ROAD ACROSS STATE WATERS CROSSING IS
ERODING ON SOUTH SIDE OF CROSSING. **Install or repair
required BMPs per Rule 1002.f.****

**PHOTO 4: CLOSER IMAGE OF EROSION FROM PREVIOUS
PHOTO (#3).**

Inspection Photos
Location Name: TIERA 11-21
API #: 05-071-09073
INSP. #:695100640



PHOTO 5: ANOTHER ANGLE OF EROSION FROM PHOTO #3.

PHOTO 6: ROAD ACROSS STATE WATERS CROSSING IS ERODING ON NORTH SIDE OF CROSSING. **Install or repair required BMPs per Rule 1002.f.**

Inspection Photos
Location Name: TIERA 11-21
API #: 05-071-09073
INSP. #:695100640



PHOTO 7: ANOTHER ANGLE OF EROSION FROM PREVIOUS PHOTO (#6).