

Location

Lease Road:

	Type Main		
comment:	PHOTO 3-8: STORMWATER DRAINAGE DITCH ON UPSLOPE SIDE OF ROW WEST OF LOCATION IS WASHED OUT.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date:	07/06/2019

Overall Good:

Signs/Marker:

	Type OTHER		
Comment:	PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS INACCURATE		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	07/06/2019

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

			corrective date
Type: Deadman # & Marked # 4			
Comment:			
Corrective Action:		Date:	
Type: Bradenhead # 1			
Comment: IS PLUMBED TO SURFACE			
Corrective Action:		Date:	
Type: Ancillary equipment # 1			
Comment: TELEMETRY EQUIPMENT			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 263050 Type: WELL API Number: 071-07603 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP INSPECTION TO DOC# 687902522. CORRECTIVE ACTION WAS ADDRESS HOWEVER THERE ARE NEW CORRECTIVE ACTIONS.	beardsit	05/06/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402034153	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816283
695100598	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816277