



**Location**

<b>Lease Road:</b>			
	Type	Access	
comment:	PHOTO 3: CULVER ON ROW NORTHWEST OF LOCATION IS PLUGGED. PHOTO 4: SEDIMENT HAS FILLED STORMWATER DRAIN ON UPSLOPE SIDE OF PLUGGED CULVERT PHOTO 5: SEDIMENT HAS CAUSED STORMWATER TO CROSS ROAD JUST INFRONT OF CULVERT PHOTO 6: STORMWATER EROSION AROUND CULVERT OUTLET.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.		Date: 07/06/2019

Overall Good:

<b>Signs/Marker:</b>			
	Type	OTHER	
Comment:	PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS INACCURATE .		
Corrective Action:	Install sign to comply with Rule 210.b		Date: 07/06/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 282177 Type: WELL API Number: 071-08658 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402034154	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816284">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816284</a>
695100600	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816278">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816278</a>