

Inspection Photos

Loc#324752

Operator: Sandridge

Inspection Number: 692400961

Inspection Date: 5/7/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to West.

May 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752



Photo#2:
Fugitive dust observed

May 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752



Photo#3:
Perimeter BMPs/delineation is not apparent.



Photo#4:
Lines are draped at limits of disturbance along sagebrush and fence line.

May 7, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752



Photo#5:
Perimeter BMPs/delineation is not apparent.



Photo#6:
Perimeter BMPs/delineation is not apparent..

May 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752



Photo#7:
Stockpiles have no BMPs.



Photo#8:
Stockpiles have no BMPs.

May 7, 2019



Photo#9:
Rutting, sediment migration was observed.

May 7, 2019



Photo#10:
Rutting, sediment migration was observed.



Photo#11:
Lack of appropriate BMPs at South side of site.

May 7, 2019



Photo#12:
Lack of appropriate BMPs at South side of site.