

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2019

Submitted Date:

05/06/2019

Document Number:

692601783

FIELD INSPECTION FORM

Loc ID 324822 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212933	WELL	TA	08/01/2018	GW	061-06294	SHOTTON 1	SI

General Comment:

5 Year MIT

Location						
Lease Road:						
Type	Access					
comment:	Trail through farm ground					
Corrective Action:					Date:	
Overall Good: <input checked="" type="checkbox"/>						
Signs/Marker:						
Type	WELLHEAD					
Comment:	Lease sign by meter shed					
Corrective Action:					Date:	
Type	TANK LABELS/PLACARDS					
Comment:	Stickers on tank					
Corrective Action:					Date:	
Emergency Contact Number:						
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>
Overall Good: <input checked="" type="checkbox"/>						
Spills:						
Type	Area	Volume				
In Containment: No						
Comment:	<input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?						
Fencing/:						
Type	OTHER					
Comment:	Wire fence around meter shed					
Corrective Action:					Date:	
Equipment:						
					corrective date	
Type:	Ancillary equipment	# 2				
Comment:	Electric panel and cathodic rectifier					
Corrective Action:					Date:	
Type:	Gas Meter Run	# 1				
Comment:						
Corrective Action:					Date:	
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	STEEL AST		38.422290,-103.003200	
Comment:	Steel tank on west side of location					
Corrective Action:					Date:	
Paint						

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms will need maintenance for capacity before put back into production				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 212933 Type: WELL API Number: 061-06294 Status: TA Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Pumped 58bbls water down csg and well wouldn't load. Once fluid reached surface, well went on a vacuum.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan Date: 05/16/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402035681	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817486
692601784	Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817484