

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

UNUSED EQUIPMENT

Comment:

Unused equipmet, PU is not connected to well head horses head is gone. No tubing or rods

Corrective Action:

Comply with Rule 603.f .

Date: 01/01/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 201870 Type: WELL API Number: 001-07274 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: PU is not hooked to WH tubing and rods are gone. Well is not plumbed to flow line. According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to be TEMPORARILY ABANDON.

Corrective Action: According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to be TEMPORARILY ABANDON. Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3)

Date: 10/14/2018

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 5/13/19 at approximately 1000 I, Inspector Justin Medina conducted an on-site inspection at Fritzler Resources INC Linnebur 24-1 001-08525 in Adams County Colorado. While there, I observed Temporarily Abandoned well This is a follow up inspection from document # 688400348 All CA are delinquent During this inspection the following possible compliance issues were observed: Unused equipmet, PU is not connected to well head horses head is gone. No tubing or Rods 1/1/19 PU is not hooked to WH tubing and rods are gone. Well is not plumbed to flow line. According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to be TEMPORARILY ABANDON. According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to be TEMPORARILY ABANDON. Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3) 10/14/18 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	05/13/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100938	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822472