

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2019

Submitted Date:

05/13/2019

Document Number:

685100935

FIELD INSPECTION FORMLoc ID 320225 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

10 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	left msg 9/21
Gomez, Jason		jason.gomez@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
,		dnr_cogccenforcement@state.co.us	Code Enforcement

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203117	WELL	SI	02/01/2016	GW	001-08525	LINNEBUR 24-1	TA

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	ROAD INTO LOCATION NEEDS TO BE REBUILT		
Corrective Action	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S.	Date:	10/06/2017
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	11/01/2018
Type	TANK LABELS/PLACARDS		
Comment:	NO PLACARDING ON PROD TANK		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/06/2017
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused 2" pipe by well head and pit		
Corrective Action:	Comply with Rule 603.f .	Date:	11/01/2018
Type	WEEDS		
Comment:	CONTROL WEEDS ON LOCATION AND ROAD WAY		
Corrective Action:	Comply with Rule 603.f .	Date:	10/18/2018
Type	OTHER		
Comment:	No cap on load line of production tanks		
Corrective Action:	Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.	Date:	10/11/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	FENCE NEEDS REPAIRED AROUND PIT		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	09/21/2017
Equipment:			
Type: Plunger Lift	# 1	corrective date	
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 0		
Comment:	No Bird protector on separator		
Corrective Action:	Net or fence pit to prevent access per rule 902.d.	Date:	05/20/2019
Type:	#		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead not plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.955090,-103.935000
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate berms around tank(s)			
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.			Date:
				10/06/2017

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:



Inspected Facilities									
Facility ID:	203117	Type:	WELL	API Number:	001-08525	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: _____									
Comment: <input type="text" value="TA"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Barbwire. Fence around pit in disrepair.

Corrective Action

Location is within a designated setback location, install fencing per Rule 604.c.(2)M.Date: 09/21/2017**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/13/19 at approximately 1000 I, Inspector Justin Medina conducted an on-site inspection at Fritzler Resources INC Linnebur 24-1 001-08525 in Adams County Colorado.</p> <p>While there, I observed Temporarily Abandoned well</p> <p>This is a follow up inspection from document # 685503722 & 88400352</p> <p>All CA are delinquent as of 10/6/17</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>ROAD INTO LOCATION NEEDS TO BE REBUILT</p> <p>Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. 10/6/17</p> <p>Sign not posted or information inaccurate at well(s) or battery</p> <p>Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. 11/1/18</p> <p>NO PLACARDING ON PROD TANK</p> <p>Install sign to comply with Rule 210.d. 10/6/17</p> <p>Unused 2" pipe by well head and pit</p> <p>Comply with Rule 603.f . 11/1/18</p> <p>No cap on load line of production tanks</p> <p>Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O. 10/11/18</p> <p>CONTROL WEEDS ON LOCATION AND ROAD WAY</p> <p>Comply with Rule 603.f . 10/18/18</p> <p>FENCE NEEDS REPAIRED AROUND PIT</p> <p>Location is within a designated setback location, install fencing per Rule 604.c.(2)M. 9/21/17</p> <p>Inadequate berms around tank(s)</p> <p>Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B. 10/6/17</p> <p>No Bird protector on separator</p> <p>Net or fence pit to prevent access per rule 902.d. 5/20/19</p> <p>Barbwire. Fence around pit in disrepair.</p> <p>Location is within a designated setback location, install fencing per Rule 604.c.(2)M. 9/21/17</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	05/13/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402043301	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822520
402043336	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822546
685100936	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822471