

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 1 Tracking pad



Photo 2 loc pic

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 3 loc pic

Photo 4 loc pic

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 5 loc pic

Photo 6 loc pic

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 7 loc pic

Photo 8 loc pic

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 9 Improper chemical Handling



Photo 10 Chemical storage. Chemical's appear to have spilled outside containment.

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Colorado Oil and Gas Conservation Commission
40.07024, -104.92698, 1538.0m
May 14, 2019 13:04:21



Colorado Oil and Gas Conservation Commission
40.07014, -104.92659, 1532.9m
May 14, 2019 13:04:58

Photo 11 Improper chemical storage not on secondary containment. Stained soil from what appears to be torn bag.

Photo 12 Protection of soils: appears crew is pushing up mud and gravel from location onto top soil pile.

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 13 stained soil pushed in drainage ditch for location drainage.

Photo 14 Protection of soils: appears crew is pushing up mud and gravel from location onto top soil pile. Stained soil and debris also being pushed on top soil.

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 15 stained soil pushed in drainage ditch between location and top soil pile.

Photo 16 Storm water: reel developing on edge of location next to topsoil pile

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 17 stained soil pushed in drainage ditch between location and top soil pile.

Photo 18 Protection of soils: Mud appears to be being pushed of location on top soil pile

Inspection Photos
Location Name: Buddy 7-15HZ
Location ID: 458702



Photo 19 drainage ditch between location and top soil pile.

Photo 20 loc pil