

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2019

Submitted Date:

05/08/2019

Document Number:

687904717

**FIELD INSPECTION FORM**

Loc ID 326647 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 18 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261495	WELL	PR	03/28/2002	GW	067-08524	ORAN W SHORT A 2	PR

**General Comment:**

[Site inspection with photos at the end of this report.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Posted on sign at tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on sign at entrance.		Date: _____
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds are beginning to grow within the 25 feet area of a fired vessel. Weed spraying should take place.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Cattle panels around wellhead.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Deadman # & Marked			corrective date
# 1			
Comment:	One rig anchor marked, the other 3 on location are not marked.		
Corrective Action:	Comply with Rule 1003.a.		Date: <u>05/23/2019</u>
Type: Flow Line			
#			
Comment:	1-3" flowline from wellhead to separator. 1-1" flowline from separator to pump jack engine fuel gas. 1-2" flowline from separator dump valve to produced water tank. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg.		
Corrective Action:			Date:
Type: Bradenhead			
# 1			

Comment:	PVC bradenhead access.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:	On separator stack.		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	Pump jack engine exhaust muffler is creating localized soil staining. Repair and/or alternative means of muffler relocation may be necessary. And engine oil day tank also has localized stained soil around the base of the spill prevention containment.		Date:	
Corrective Action:	Comply with Rule 907.e.		Date:	06/08/2019
Type: Gas Meter Run	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV STEEL		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 261495 Type: WELL API Number: 067-08524 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Rip Rap	Pass			Material Handling And Spill Prevention	Pass	Spill prevention for engine oil day tank.
Compaction	Pass	Compaction	Pass			

Comment: [Spill prevention for day tank is in place, see CA under equipment tab, pumpjack for localized oily waste around base. Just another note, that an irrigation line coming from pasture from the north, feeds onto location be entrance and flows through culvert across location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402037028	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818538">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818538</a>
687904718	marked rig anchor.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818499</a>
687904719	Localized stained from muffler	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818500</a>
687904720	SE rig anchor	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818501</a>
687904721	SW rig anchor	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818502</a>
687904722	NW rig anchor	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818503">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818503</a>
687904723	Localized Stained gravel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818504">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818504</a>
687904724	Weeds in respect to fired vessel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818505">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818505</a>