

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2019

Submitted Date:

05/08/2019

Document Number:

689703124

FIELD INSPECTION FORM

Loc ID 335383 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256628	WELL	PR	01/18/2000	GW	045-07478	PUCKETT 31-23D	PR
256734	WELL	PR	08/09/2000	GW	045-07491	PUCKETT 31-14D	PR
256735	WELL	PR	08/30/2000	GW	045-07492	PUCKETT 31-24D	PR
256803	WELL	PR	01/01/2011	GW	045-07498	PUCKETT 6-31D	PR

General Comment:

COGCC Inspection Report Summary
On Tuesday 05/07/2019 at approximately 1330 hours, I, Inspector Mike Longworth, conducted a field inspection at Caerus PUCKETT 31-23D, at Location # 335383 in Garfield County, Colorado.
While there, I observed production of wells.
During this inspection the following possible compliance issues were observed:
Run off storm water flowing on to and across location. BMPs (ditches berms and waddles) need maintained. Shale, rock and sediment sloughing off of cut slope against tank berm.
Install or repair required BMPs per Rule 1002.f.
Corrective Action date 06/08/2019

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

--	--	--	--

Inspected Facilities									
Facility ID:	<u>256628</u>	Type:	<u>WELL</u>	API Number:	<u>045-07478</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>256734</u>	Type:	<u>WELL</u>	API Number:	<u>045-07491</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>256735</u>	Type:	<u>WELL</u>	API Number:	<u>045-07492</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>256803</u>	Type:	<u>WELL</u>	API Number:	<u>045-07498</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Run off storm water flowing on to and across location. BMPs (ditches berms and waddles) need maintained. Shale, rock and sediment sloughing off of cut slope against tank berm.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/08/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402036099	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817790
689703125	Inspection 689703124 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817780