

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/08/2019

Document Number:

689802617

FIELD INSPECTION FORM

Loc ID 313308	Inspector Name: Waldron, Emily	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 97810 Name of Operator: EOG Y RESOURCES INC Address: 105 SOUTH 4TH ST City: ARTESIA State: NM Zip: 88210				Findings: 4 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Allman, Stephanie	307-382-4005	stephanie_allman@eogresources.com	
Elgin, Jerry		jelgin@mspartners.com	
Gallenbeck, Danny		dgallenbeck@ctfieldsvcs.com	
Blaylock, Connie		cblaylock@mspartners.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285957	WELL	SI	05/23/2018	GW	081-07328	LANDING STRIP FEDERAL 1	SI

General Comment:**COGCC Inspection 689802617 Report Summary**

On Thursday, 05/02/2019, at approximately 11:00, I, Inspector Emily Waldron, conducted a field inspection at EOG Y Resources Inc Landing Strip Federal 1, at API 05-081-07328 in Moffat County, Colorado.

During this inspection the following possible compliance issues were observed:

Stormwater Management - Sediment entering and leaving location. Stormwater BMPs have not been maintained and have become debris. Large erosion gully leaving location at southwest corner. Ditch below location at this gully is full of sediment and sediment is overflowing and leaving the ditch and location. Sediment entering location on the northwest side where wattles have become debris and no other BMPs were observed. See photos 2-8.

Install or repair required BMPs per Rule 1002.f, by 5/17/2019.

Form 10 document number 2304077, submitted 1/23/2019, On Hold to transfer from EOG Y Resources Inc. to Southland Royalty Company, LLC.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection 689802617 report.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	At entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-324-2658

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected Facilities									
Facility ID:	285957	Type:	WELL	API Number:	081-07328	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Sediment entering and leaving location. Stormwater BMPs have not been maintained and have become debris. Large erosion gully leaving location at southwest corner. Ditch below location at this gully is full of sediment and sediment is overflowing and leaving the ditch and location. Sediment entering location on the northwest side where wattles have become debris and no other BMPs were observed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/17/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402037096	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818675
689802642	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818650