

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2019

Submitted Date:

05/08/2019

Document Number:

696600050**FIELD INSPECTION FORM**

Loc ID 334486 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294172	WELL	PR	01/03/2008	GW	077-09467	N. VEGA 23-414	PR
294831	WELL	PR	03/05/2008	GW	077-09514	NVEGA 24-121	PR
294832	WELL	PR	03/05/2008	GW	077-09515	NVEGA 24-124	PR
294833	WELL	PR	03/05/2008	GW	077-09516	NVEGA 24-114	PR
294834	WELL	PR	03/05/2008	GW	077-09517	NVEGA 23-421	PR
294838	WELL	PR	03/05/2008	GW	077-09518	NVEGA 23-411	PR
297169	WELL	PR	07/16/2008	GW	077-09684	NVEGA 24-111R	PR

**General Comment:**[Routine FIU General Field Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [911 / Posted Emergency Contact Number 1-800-891-6191](#)Corrective Action:  Date: Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 7	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	294172	Type:	WELL	API Number:	077-09467	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294831	Type:	WELL	API Number:	077-09514	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294832	Type:	WELL	API Number:	077-09515	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294833	Type:	WELL	API Number:	077-09516	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294834	Type:	WELL	API Number:	077-09517	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294838	Type:	WELL	API Number:	077-09518	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	297169	Type:	WELL	API Number:	077-09684	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Compaction	Pass					
Silt Fences	Fail					
Berms	Fail					
		Sediment Traps	Pass			
		Check Dams	Pass			
		Culverts	Pass			
		Drains	Pass			
Gravel	Pass					
Slope Roughening	Pass					
Waddles	Pass					
Ditches	Pass					

Comment: Berms around location have been push down, this is the cause of soil leaving location. Silt fence needs maintenance.  
BMP's need repaired or are not being maintained at this time.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/10/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 05/07/2019 at approximately 0155 hours, I, Inspector Dougo Wentzel, conducted a field inspection at the Laramie Energy, North Vegas 23-414, API # 077-09467, in MesaCounty, Colorado.</p> <p>While there, I observed only a Production Operation.</p> <p>During this inspection, compliance issues were observed.</p> <p>Storm water issues were found at time of inspection.</p> <p>It appeared that during snow moving operations, the equipment damaged the berm surrounding the location.</p> <p>In addition to the berm needing maintenance, the silt fence needs repaired on the SE side of location.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	wentzeld	05/07/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402035944	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817685">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817685</a>

696600051	Inspection 696600050 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817680">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817680</a>
-----------	--------------------------------	---

