

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2019

Submitted Date:

05/09/2019

Document Number:

687904737**FIELD INSPECTION FORM**Loc ID 312126 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Roland, Kandis		kroland@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214662	WELL	PR	12/01/2018	GW	067-06266	TIFFANY EAST 2-17	PR
299610	WELL	PR	02/10/2010	GW	067-09647	TIFFANY EAST 3-17	PR

**General Comment:**

Site inspection of equipment on site. Photos at the end of this report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signs located on fence at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact information posted on sign at wellhead.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Pump Jack on well Tiffany East #3-17 Is not in use and the head has been pulled off and a plunger lift has been installed. If pumpjack is not going to be put back into use, it is considered unused equipment and needs to be removed.		
Corrective Action:	Comply with Rule 603.f.	Date:	08/09/2019

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire around location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	See unused equipment CA under housekeeping.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellheads		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 8		

Comment:	2-3" flowlines from wellhead to separator. 2-3" flowlines from separator to meter house. 2-2" flowlines from separator dump to offsite produced water gathering system. 2-4" flowlines from meter house to offsite fathering system.			
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 2			
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 214662 Type: WELL API Number: 067-06266 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 299610 Type: WELL API Number: 067-09647 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
				Material Handling And Spill Prevention	Pass	spill prevention for chemical injection.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402039105	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820149">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820149</a>
687904739	Unused pumpjack	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820145">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820145</a>
687904740	Unused pumpjack	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820146">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820146</a>