

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> TABOR 8	<b>Facility ID:</b> 114852
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> TODD & MAHAN INC / 88570	
<b>Updated Operator:</b> MEYER OIL COMPANY - 57000	
<b>Form 15 Pit Permit Doc #:</b> NA	<b>Permit Date:</b> NA
<b>Related Facilities:</b> API # 05-013-06234 (Facility ID 206739), API # 05-013-06198 (Facility ID 206703); shared site	

<b>County:</b> Boulder			
<b>Township:</b> 2N	<b>Range:</b> 69W	<b>Section:</b> 21	<b>QQ:</b> NWNE
<b>Original Latitude/ Longitude:</b> 40.128876 / -105.11913			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #: NA  | Date: NA         |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 580936   | Date: 7/17/1987  |
|                                     | Doc #: 500137359  | Date: 11/15/1995 |
|                                     | Doc #:  | Date:            |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:                                     | Date:            |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:   | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:   | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:  | Date:            |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 114851 (shared site with Carlson 21-1) |                  |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached)                                   |                  |
| <input type="checkbox"/>            | Other:  |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date:**

#### Timing of Pit Closure:

013-06234: Well PA 12/22/1993, Passed PA inspection 11/15/1995.

013-06198: Well PA 10/1/1991, Passed PA inspection 7/28/1992.

#### Pit Status Review Summary:

Shared site with Carlson 21-1 (pit ID 114851). Based on records review, there is no evidence that there was a pit on location. Inspection reports document a concrete water vault on location. Well was plugged and passed final reclamation inspection 11/15/1995. Pit status changed to closed.