

# Inspection Photos

ID: 150131

Operator: STRACHAN EXPLORATION INC

Inspection Date: 5/15/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 150131 | Date: 5/15/2019

## Inspection Photos



**Photo 1.** The sign at the site is not legible.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 5/15/2019



## Inspection Photos



**Photo 2.** There was a dripping water leak coming from the condensate tank. Operator was notified the same day.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 5/15/2019



## Inspection Photos



**Photo 3.** There is various unused debris at the site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 5/15/2019



## Inspection Photos



**Photo 4.** The berms around the tanks are not sufficient. The fence is not sufficient to prevent livestock entry.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 5/15/2019