

Inspection Photos

API: 05-025-06020

Operator: CRAZY 8 ENERGY LLC

Inspection Date: 5/15/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-025-06020 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing northwest toward the location. The pits have been closed however the site has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 5/15/2019

Inspection Photos



Photo 2. There is a pile of liner debris that has not been disposed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 5/15/2019

Inspection Photos



Photo 3. The ditch directed toward the pit needs to be filled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 5/15/2019

Inspection Photos



Photo 4. The ditch at the north side of the location that wraps around to the southwest must be filled in and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 5/15/2019

Inspection Photos



Photo 5. North side of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 5/15/2019

Inspection Photos



Photo 6. The ditch around the south side of the location must be filled in and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 5/15/2019

Inspection Photos



Photo 7. South side of the location facing north. Reclamation has not been performed and soils are not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 5/15/2019