

# Inspection Photos

API: 05-073-06615

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 5/15/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06615 | Date: 5/15/2019

## Inspection Photos



**Photo 1.** Facing northeast along the reclaimed access road. There are areas along the road where vegetation is not establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06615 | Date: 5/15/2019



## Inspection Photos



**Photo 2.** Facing northeast further along the road. Vegetation is establishing well in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06615 | Date: 5/15/2019



## Inspection Photos



**Photo 3.** Further along the road. Vegetation is not establishing well in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06615 | Date: 5/15/2019



## Inspection Photos



**Photo 4.** Facing east toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06615 | Date: 5/15/2019



## Inspection Photos



**Photo 5.** Facing north toward the location. The northern portion of the location is establishing vegetation well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06615 | Date: 5/15/2019



## Inspection Photos



**Photo 6.** Facing south at the location. The southern portion is not establishing vegetation and needs to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06615 | Date: 5/15/2019



## Inspection Photos



**Photo 7.** Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, Pas smi, among other native plants.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06615 | Date: 5/15/2019