

Inspection Photos

API: 05-061-06866

Operator: NAVEX RESOURCES LLC

Inspection Date: 5/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06866 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing east along the former access road. A two track is still visible.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06866 | Date: 5/15/2019

Inspection Photos



Photo 2. Facing east at the location. Vegetation is establishing however, there is a dominance of undesirable weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06866 | Date: 5/15/2019

Inspection Photos



Photo 3. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06866 | Date: 5/15/2019

Inspection Photos



Photo 4. Facing southwest at the location. This area has a dominance of weed growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06866 | Date: 5/15/2019

Inspection Photos



Photo 5. View of vegetation cover. There are perineal species establishing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06866 | Date: 5/15/2019

Inspection Photos



Photo 6. Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, Pas smi, among other native plants.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06866 | Date: 5/15/2019