

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2019

Submitted Date:

05/14/2019

Document Number:

693900290**FIELD INSPECTION FORM**
 Loc ID 306966 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		sabre.beebe@bpx.com	<a href="#">All Inspections</a>
,		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285561	WELL	PR	07/12/2006	GW	067-09199	EMMETT WOLTER 2	RI

**General Comment:**[This is an interim reclamation and stormwater inspection.](#)

Inspected Facilities									
Facility ID:	285561	Type:	WELL	API Number:	067-09199	Status:	PR	Insp. Status:	RI

--

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment Unused equipment stored within the western project area.Corrective Action Remove unused equipment.Date 06/28/2019

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? In Production areas stabilized ?           

1003c. Compacted areas have been cross ripped?           

1003d. Drilling pit closed?            Subsidence over on drill pit?           

Cuttings management:           

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? In Segregated soils have been replaced?           

## RESTORATION AND REVEGETATION

Cropland

Top soil replaced            Recontoured            Perennial forage re-established In

Non-Cropland

Top soil replaced            Recontoured            80% Revegetation           

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%           

TRANSECT RESULTS OF REFERENCE AREA%           

TOTAL % OF DESIRABLE VEGETATION COVER           

VEGETATIVE COVER           

1003 f. Weeds Noxious weeds? F

Comment Project area is surrounded by irrigated crop field. Revegetation is progressing within the outer revegetation areas. Approximately 500 musk thistles observed within the project area.

Corrective Action Control weeds by June 1, 2019.

Date 06/01/2019

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started:            Date Final Reclamation Completed:           

Final Land Use:           

Reminder:           

Comment:           

Well plugged            Pit mouse/rat holes, cellars backfilled           

Debris removed            No disturbance /Location never built           

Access Roads            Regraded            Contoured            Culverts removed           

Gravel removed           

Location and associated production facilities reclaimed            Locations, facilities, roads, recontoured           

Compaction alleviation            Dust and erosion control           

Non cropland: Revegetated 80%            Cropland: perennial forage           

Weeds present            Subsidence           

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%           

TRANSECT RESULTS OF REFERENCE AREA%           

TOTAL % OF DESIRABLE VEGETATION COVER           

VEGETATIVE COVER           

Comment:           

Corrective Action:           

Date           

Overall Final Reclamation           

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater erosion appears to be controlled at this time.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402043980	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823012">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823012</a>
693900291	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822979">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822979</a>