

Inspection Photos  
Location Name: Cuykendall-Lauck #2  
Location ID: 317921



Pic 1



Pic 2

Inspection Photos  
Location Name: Cuykendall-Lauck #2  
Location ID: 317921



**Pic 3 stained soil in motor house**



**Pic 4**

Inspection Photos  
Location Name: Cuykendall-Lauck #2  
Location ID: 317921



COLORADO OIL AND GAS CONSERVATION COMMISSION  
40.13934, -104.48155, 4835.2ft, 217°  
05/21/2019 11:10:08



COLORADO OIL AND GAS CONSERVATION COMMISSION  
40.13929, -104.48161, 4834.4ft, 345°  
05/21/2019 11:10:24

**Pic 5 stained soil under valve**

**Pic 6 unused equipment by oil tank**

Inspection Photos  
Location Name: Cuykendall-Lauck #2  
Location ID: 317921



**Pic 7 leaking valve behind tank**



**Pic 8 unused equipment/trash in front of separator house**

Inspection Photos  
Location Name: Cuykendall-Lauck #2  
Location ID: 317921



Pic 9



Pic 10 tank with no content label, capacity, or NFPA

**Inspection Photos**  
**Location Name: Cuykendall-Lauck #2**  
**Location ID: 317921**



**Pic 11**