

**Weaver Ridge 14-15H & 14-15H2**

**API: 05-103-11932**

**Inspection: 679704153**



**Photo 1. Location looking west.**



## Weaver Ridge 14-15H & 14-15H2

API: 05-103-11932

Inspection: 679704153



**Photo 2. Oily waste on ground at pump jack exhaust.**



**Photo 3. Oil sheen on water at tank off loading.**

## Weaver Ridge 14-15H & 14-15H2

API: 05-103-11932

Inspection: 679704153



**Photo 4. Container at pump jack without contents label.**