

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

679704046**FIELD INSPECTION FORM**Loc ID 315193 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Jordan	970-563-4000	maralextechjr@gmail.com	<a href="#">All inspections</a>
, Maralex	970-858-8550	aak@gvep.net	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Graves, Jim	970-712-0099	mrinc20@qwestoffice.net	<a href="#">Operations Manager</a>
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230392	WELL	SI	09/11/1995	GW	103-08054	TRAIL CANYON 20-1	TA

**General Comment:**[COGCC Inspection Report Summary.](#)

On 5/14/2019 at approximately 10:00, inspector Rick Moran, conducted a follow up inspection at Maralex Resources well Trail Canyon 20-1 in Rio Blanco county in reference to the following documents:

- 1) FIR 675102595 dated 6-13-2016.
- 2) FIR 679701493 dated 10-25-2018.
- 3) Warning letter 401499076.

The following compliance issues were observed as uncompleted:

- 1) MIT

The additional compliance issues were identified:

- 1) Stormwater management. Photo 2 & 3. Complete by 6-17-2019.
- 2) Part of separator housing lying on ground. Photo 5. Complete by 6-17-2019.
- 3) Stormwater debris. Photo 4 & 6. Complete by 6-17-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704046.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	970-858-8550		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Brush and wood washed unto the location including wrapped up next to the wellhead and separator.		
Corrective Action:	Comply with Rule 603.f .		Date: 06/17/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Fencing bent.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Part of the separator outside housing is lying on the ground.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 06/17/2019

<b>Venting:</b>			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 230392 Type: WELL API Number: 103-08054 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last recorded production October 2012. No MIT on file.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Prior stormwater flow through the entire location.](#)

[A creek is along the southwest edge of the location. No stormwater ditch present on the southeast edge of the location to prevent the creek from flowing through the location, including the well head, during heavy runoffs. Also no stormwater BPM present along the northeast edge of the location along the hill cut.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 06/17/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: \_\_\_\_\_ Pit ID: \_\_\_\_\_ Lat: 39.688320 Long: -108.761420

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment: [FIR inspection 663800290 dated 4-20-2012 inventoried a pit on the location. Currently no visible surface imprint of a pit. The extensive stormwater through the entire location would likely have filled any pit present with dirt.](#)

[The coordinate provided with this inspection is next to the separator.](#)

Corrective Action

Date:

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard: NO

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402044774	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823508">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823508</a>
679704047	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823501</a>