

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2019

Submitted Date:

05/15/2019

Document Number:

693800117**FIELD INSPECTION FORM**
 Loc ID 312709 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10310Name of Operator: FRAM OPERATING LLCAddress: 5525 N UNION BLVD #200City: COLORADO State: CO Zip: 80918**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Hickam, Hannah		hannah.hickam@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276950	WELL	SI	01/11/2010	GW	077-08864	JENSEN 12-1	SI

General Comment:

Inspection performed 5/13/2019 in response to landowner concerns of flowline risers, well leaks and operator bankruptcy filing.
Well is Shut in and secured with no leaks. Staining from previously repaired leak at separator.
Unused flowlines and gathering line risers are blind flanged with valves locked out/tagged out and no leaks. Lines are not in service.

Location

Lease Road:			
Type	Access		
comment:	Thru private land. No maintainance performed by operator.		
Corrective Action	L	Date:	
Type	Main		
comment:	Kannah Creek Rd.		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	888-518-6176
Corrective Action:	
Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: Wellhead Shut in and Locked out/tagged out. No spills or leaks observed.

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 2		
Comment:	2"-4" production line and 8" gathering line. Blind flanged and locked out/tagged out. Not in service.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Stained soil from previously repaired leak on N side of separator.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Last calibrated 11/2009.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		38.940399,-108.297643
Comment: Disconnected. Not in service.					

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 276950 Type: WELL API Number: 077-08864 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment:

Well shut in 12/2009. Last MIT 10/16/2013.
Attempted Bradenhead test 10/30/2018. Unable to perform test. No valve on surface casing. 9 7/8" casing cut BGL, with no spool installed. Cement to surface.
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Corrective Action:

No current MIT on record or delinquent as required by Rule 326.

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: [No other BMPs or access road maintainance performed by operator.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402045141	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823848
693800118	Inspection photos 5/13/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823840