

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2019

Submitted Date:

05/22/2019

Document Number:

679704175**FIELD INSPECTION FORM**

| | | | | |
|---|--------------------------------|---|-------------------|--|
| Loc ID 316496 | Inspector Name: Moran, Rick | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 8 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested |
| Operator Information: OGCC Operator Number: <u>6720</u> Name of Operator: <u>ROBERT L BAYLESS PRODUCER LLC</u> Address: <u>621 17TH ST STE 2300</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80293</u> | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------------------------------|
| Trujillo, Helen | | notices@rlbayless.com | All inspections |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 282581 | WELL | PR | 07/29/2006 | GW | 103-10671 | WEAVER RIDGE 27-1 | PR |

General Comment:[COGCC Inspection Report Summary.](#)

On 5/21/2019 at approximately 15:00, inspector Rick Moran, conducted a follow up inspection at Robet L Bayless well Weaver Ridge 27-1 in Rio Blanco county of FIR document 679702494.

The following compliance issues were identified as resolved:

- 1) Unused container.
- 2) Tank capacity on 2 of 3 tanks.

The following compliance issues were observed as uncompleted:

- 1) Container label. Photo 2. Completed by 3-11-2019.
- 2) Tank capacity on 1 tank. Photo 3. Completed by 3-11-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704175.

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | One tank with volume capacity missing on label. | | |
| Corrective Action: | Install sign to comply with Rule 210.d | Date: | 03/11/2019 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Black container at pump jack without label. | | |
| Corrective Action: | Install sign to comply with Rule 210.d | Date: | 03/11/2019 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 505-327-0880

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|-----------------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 2 | | |
| Comment: | One container of methanol and 1 container of motor oil. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | 300 BBLs | STEEL AST | | 39.937730,-109.047710 |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 39.937730,-109.047710 |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 282581 | Type: | WELL | API Number: | 103-10671 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Pump jack producing at time of inspection. | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [No apparent soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 679704176 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4829645 |