

Inspection Photos
Operator: BP America
Location/API #: 067-06780
Date: 5-17-2019



Photo 1. View of the western project area from the southwestern corner facing northward.



Photo 2. View of musk thistle (*Carduus nutans*) seedlings and hoary cress (*Cardaria draba*) within the southern project area.



Photo 3. View of hoary cress (*Cardaria draba*) infestation within the southern pipeline alignment.



Photo 4. View of erosional channels approximately 2 feet wide and 1 foot deep within the southeastern project area.