

Inspection Photos
Operator: BP America
Location/API #: 067-08883
Date: 5-17-2019



Photo 1. View of the northern project area from the northeastern corner facing westward.



Photo 2. View of cut-slopes in the northwestern project area that are not stabilized.



Photo 3. View of stormwater controls along the access road that are full of sediment and need maintenance.



Photo 4. View of the eastern project area from the southeastern corner facing northward. Area is infested with hoary cress (*Cardaria draba*)