


Inspection Photos
Location Name: Millard #43-30
Location ID: 333199



Pic 1 separator lines not plugged.

Pic 2 stained soil possible leak on oil tank

Inspection Photos
Location Name: Millard #43-30
Location ID: 333199



Pic 3

Pic 4

Inspection Photos
Location Name: Millard #43-30
Location ID: 333199



Pic 5

Pic 6 chemical tank with no containment no placard.