

Inspection Photos
Location Name: UPRR 43 Pan AM H #6
Location ID: 318050



Photo 1 WH

Photo 2 WH sign unlegible

Inspection Photos
Location Name: UPRR 43 Pan AM H #6
Location ID: 318050



Photo 2 Horses head bridle not attached to rods.



Photo 4 Electric power to PU is in the off position at breaker box. Well cannot pump on timer.