

Inspection Photos
Location Name: Hopkins 41C-19#2
Location ID: 317973



Photo 1 WH sign. Storm water improper storage of chemicals.



Photo 2 WH

Inspection Photos
Location Name: Hopkins 41C-19#2
Location ID: 317973



Photo 3 Trash on well site location.



Photo 4 Power at breaker box is in off position.

Inspection Photos
Location Name: Hopkins 41C-19#2
Location ID: 317973



Photo 5 TNK BTRY



Photo 6 No NFPA placard and no tank volume on produced water tank.

Inspection Photos
Location Name: Hopkins 41C-19#2
Location ID: 317973



Photo 7 Trash: **TV**



Photo 8 Sep

Inspection Photos
Location Name: Hopkins 41C-19#2
Location ID: 317973



Photo 9 Trash: 5 buckets. Stained soil, Mechanical issues appears piping is leaking on ground.



Photo 10 Unused equipment: fiber glass and steel pipe next to sep.

Inspection Photos
Location Name: Hopkins 41C-19#2
Location ID: 317973



Photo 11 Trash on site next to sep



Photo 12 Trash on battery site.