

Inspection Photos
Location Name: Lauridson Tank Battery
Facility ID: 457409



Photo 1 Unused equipment: Separator, appears all flow line piping has been removed.



Photo 2 Unused equipment: Separator, appears all flow line piping has been removed.

Inspection Photos
Location Name: Lauridson Tank Battery
Facility ID: 457409



Photo 3 Location pic



Photo 4 flow lines to tank valves are closed

Inspection Photos
Location Name: Lauridson Tank Battery
Facility ID: 457409



Colorado Oil and Gas Conservation Commission
40.05106, -104.92441, 1534.1m
May 22, 2019 14:34:48

Photo 5 TNk BTRY. Inadequate berms material appears to be pushed up and dot compacted.



Colorado Oil and Gas Conservation Commission
40.05107, -104.92441, 1533.1m
May 22, 2019 14:34:38

Photo 6 loc pic. Spoil piles with out BMP's, Safety fence in disrepair.

Inspection Photos
Location Name: Lauridson Tank Battery
Facility ID: 457409



Photo 7 flow line valves to crude oil tank closed



Photo 8 excavation safety fence in disrepair. No BMP's in place of excavation.

Inspection Photos
Location Name: Lauridson Tank Battery
Facility ID: 457409



Photo 9 No BMP's controlling sediment from running off excavation. Sediment being carried down natural drainage. Safety fence in disrepair.



Photo 10 Several flow lines exposed, no BMP's in place around excavation. No safety fence around open excavation.

Inspection Photos
Location Name: Lauridson Tank Battery
Facility ID: 457409



Photo 11 Several flow lines exposed, no BMP's in place around excavation. No safety fence around open excavation.



Photo12 Safety fence in disrepair. No BMP in place on open excavation for run on.