

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2019

Submitted Date:

05/22/2019

Document Number:

687904798

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
306805 _____ Stewart, Joseph _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Hughes, Jim		jimo.hughes@state.co.us	
,	970-563-4000	maralextech@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267561	WELL	PR	08/05/2003	GW	067-08800	MOLLIE CORYNNE 33-7-2 2A	PR

General Comment:

Site inspection with numbered photos at the end of this inspection report. Previous inspection document #685301373 which shows last inspected on 9/12/2016.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted on fence at wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on sign.		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	TRASH		
Comment:	Used rags and pads around equipment. See photo #3,4,6,8		
Corrective Action:	Clean up trash and dispose of properly per Rule 603.f.		Date: <u>06/01/2019</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment parts sitting on concrete and plastic tub out front of fence. See photo #2,3		
Corrective Action:	Remove unused parts per Rule 603.f.		Date: <u>06/01/2019</u>
Type	WEEDS		
Comment:	Weeds and dead brush around equipment. See photo #2,3,8		
Corrective Action:	Control weeds per Rule 603.f.		Date: <u>06/01/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	T-post and hogwire around pumpjack.		
Corrective Action:			Date:
Equipment:			
Type: Horizontal Heated Separator # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead # 1			
Comment:	Plumbed to surface.		
Corrective Action:			Date:
Type: Prime Mover # 1			
Comment:	Natural gas engine.		
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Pumpjack gearbox seals leaking gear oil down unit and on concrete on both the east and west side of unit. See Photo #5,6,8,9		
Corrective Action:	Securely fasten fitting to ensure good mechanical condition and clean up oily waste per Rule 1002.f.(2)		Date: <u>06/22/2019</u>
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead is leaking from packing gland. See photo #7		
Corrective Action:	Repair/maintain wellhead per Rule 1002.f.(2)		Date: <u>05/29/2019</u>
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 7		
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from wellhead to separator that ties into offsite produced water gathering system. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-1" flowline from wellhead to pumpjack fuel gas. 1-2" flowline from separator to meter house. 1-2" flowline from meter house that ties into 1-6" flowline to offsite gathering system.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 267561 Type: WELL API Number: 067-08800 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention on engine oil day tank.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904801	MOLLY CORYNNE INSPECTION PHOTOS.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830070