

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

687904758**FIELD INSPECTION FORM**
 Loc ID 333710 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Azulai, .	970-563-4000	maralextech@gmail.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265538	WELL	PR	10/15/2003	GW	067-08770	JENNIE ROSE 33-7-3 1	PR

General Comment:[Site inspection with photos at the end of this report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel road access across private property.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Parts laying on 55 gallon drum that are not being used and sucker rod and timbers laying along side of pumpjack.		
Corrective Action:	Comply with Rule 603.f.		Date: 06/16/2019
Type	WEEDS		
Comment:	Weeds and vegetation around separator, meter house need to be controlled.		
Corrective Action:	Comply with Rule 603.f.		Date: 05/26/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Flow Line	# 5	corrective date	
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline form separator dump valve to offsite produced water gathering system. 1-1" flowline from separator to pumpjack fuel gas. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Engine oil with staining of gravel/soil below engine. Repair leaking equipment and remediate soil and gravel and dispose of in accordance with regulations.		
Corrective Action:	Comply with Rule 1002.f.(2)		Date: 07/16/2019
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 265538	Type: WELL	API Number: 067-08770	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing.			
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	No spill prevention on plastic barrel on separator
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil day tank.
Gravel	Pass	Gravel	Pass			

Comment: 55 gallon drum sitting at separator, with vacuum breaker hose into barrel has no spill prevention and is full. Prevent release from occurring ASAP.

Corrective Action: Comply with Rule 907.a.

Date: 06/16/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402046701	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825270
687904788	JENNY ROSE 33-7-3 1 Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825262