

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

687904777

FIELD INSPECTION FORM

Loc ID 311958 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 16 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,	970-563-4000	maralextech@gmail.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277813	WELL	PR	01/10/2006	GW	067-09049	MARY CATHERINE 33-7-3 2A	PR
294238	WELL	PR	05/11/2008	GW	067-09476	MARY CATHERINE 33-7-3 3C	PR

General Comment:

[Site inspection with photos at the end of this inspection report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel road access through locked gate.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Signs posted on meter house.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on sign.		Date:
Corrective Action:			
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around equipment need to be controlled.		
Corrective Action:	Comply with Rule 603.f.		Date: 06/16/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused wellhead valve sitting on pump jack skid needs to be removed.		
Corrective Action:	Comply with Rule 603.f.		Date: 06/16/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Pump Jack	#		corrective date
Comment:	33-7-3 #2A and #3C both have gearbox seal leaks on pumpjack and stained soil and oily waste are present along concrete.		
Corrective Action:	Comply with Rule 605.d. and Rule 907.e.		Date: 06/14/2019
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Wellhead has localized areas of stained soil and gravel and oily waste. Treat and dispose of properly.		
Corrective Action:	Comply with Rule 907.e. and Rule 1002.f.(2)		Date: 06/16/2019

Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Flow Line	# 9		
Comment:	2-2" flowlines from wellhead to separator. 2-3" flowlines from separator to meter house. 2-3" flowlines from meter house to offsite dogleg. 2-2" flowlines from separator dump valves to produced waater gathering system. 1-1" flowline from separator to pumpjack fuel gas.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 277813 Type: WELL API Number: 067-09049 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 294238 Type: WELL API Number: 067-09476 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	No spill prevention for engine oil day tanks.
Gravel	Pass	Gravel	Pass			

Comment: [Pump jack engine oil day tanks do not have spill prevention. Implement and maintain Best Management Practices \(BMP's\) to include measures such as spill prevention.](#)

Corrective Action: [Comply with Rule 1002.f.\(2\)B](#)

Date: 06/16/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402046704	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825273
687904791	MARY CATHERINE 33-7-3 2A Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825265