

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2019

Submitted Date:

05/16/2019

Document Number:

692400963**FIELD INSPECTION FORM**Loc ID 439603 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@san dridgeenergy.com	
		doverbey@sandridgeenergy.c om	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446917	WELL	AL	04/16/2019		057-06570	Mutual 0780 6-8H	RI
446918	WELL	AL	04/16/2019		057-06571	Mutual 0780 8-8H	RI
446919	WELL	AL	04/16/2019		057-06572	Mutual 0780 7-8H	RI

General Comment:

This is an Abandoned Location Inspection, for Three Wells, listed in Inspected Facilities above; APDs First Approved in 2016, Permits Abandoned 4/2/2019. The Three AL Wells have a GPS & COGCC Maps position at the recently expanded North nose of the Location, where there are Four Cellars with Conductors Set, which are purportedly related to the Four XX Wells slated for Drilling (three of which have position approx 310 ft SE of the ALs on GPS & Maps). Documents changing position of three XX Wells were not found in Files. Operator needs to determine if correct well Permits were Abandoned or otherwise explain the API# confusion.

Inspected Facilities									
Facility ID:	<u>446917</u>	Type:	<u>WELL</u>	API Number:	<u>057-06570</u>	Status:	<u>AL</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446918</u>	Type:	<u>WELL</u>	API Number:	<u>057-06571</u>	Status:	<u>AL</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446919</u>	Type:	<u>WELL</u>	API Number:	<u>057-06572</u>	Status:	<u>AL</u>	Insp. Status:	<u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: HAY MEADOW, OTHER

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: HAY MEADOW, OTHER _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: The Three AL Wells have a GPS & COGCC Maps position at the recently expanded North nose of the Location, where there are Four Cellars with Conductors Set, which are purportably related to the Four XX Wells slated for Drilling (three of which have position approx 310 ft SE of the ALs on GPS & Maps). Documents changing position of three XX Wells were not found in Files. At present there is Evidence of the AL Wells (cellars with Conductors Set); which causes them to Fail Final Reclamation.

Inspector Name: Colby, Lou

Corrective Action:	Operator needs to determine if correct well Permits were Abandoned or otherwise explain the API# confusion. Please communicate findings to Inspector so Actions needed, if any, can be pursued.	Date	05/24/2019
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402047025	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825544
692400978	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825533