

Extraction Oil and Gas - Inspection Photos 05/22/2019

Location: Hiner 36 Pad

Spill ID # 464520



Signage at well pad.



View of excavation exposing flowlines adjacent to the NW side of Hiner tank battery.

Extraction Oil and Gas - Inspection Photos 05/22/2019

Location: Hiner 36 Pad

Spill ID # 464520



**(3) 2" carbon steel flowlines exposed in the excavation;
electrical conduit/ wiring routed over the flowlines.**



**Active drip was observed on the (top) flowline pictured.
Ripples can be seen in standing water.**

Extraction Oil and Gas - Inspection Photos 05/22/2019

Location: Hiner 36 Pad

Spill ID # 464520



Large rocks wedged between and under flowlines exposed in the trench.



View from the excavation west toward heated horizontal separators. Pin flags and paint mark flowline alignments.