

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2019

Submitted Date:

05/23/2019

Document Number:

689703142**FIELD INSPECTION FORM**Loc ID 335182 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277834	WELL	PR	12/30/2005	GW	045-10797	FEDERAL PA 11-33	PR
277835	WELL	PR	01/04/2006	GW	045-10796	FEDERAL PA 311-33	PR
290637	WELL	PR	05/17/2007	GW	045-14165	FEDERAL PA 411-33	PR
290638	WELL	PR	05/17/2007	GW	045-14164	FEDERAL PA 511-33	PR
290670	WELL	PR	05/18/2007	GW	045-14170	FEDERAL PA 441-32	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 05/22/2019 at approximately 1400 hours, I, Inspector Mike Longworth, conducted a field inspection at (Operator Name) TEP RM LLC PA 11-33, at Location # 335182 in Garfield County, Colorado.

While there, I observed Production.

During this inspection the following possible compliance issues were observed:

Erosion rilling and erosion of road and shoulder of access road at entrance of location.

Corrective action: Install or repair required BMPs per Rule 1002.f.

Corrective action date: 06/23/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities						
Facility ID:	277834	Type:	WELL	API Number: 045-10797	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	277835	Type:	WELL	API Number: 045-10796	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	290637	Type:	WELL	API Number: 045-14165	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	290638	Type:	WELL	API Number: 045-14164	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	290670	Type:	WELL	API Number: 045-14170	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Check Dams						
Ditches						
		Ditches				
		Compaction				

Comment: [Erosion rilling and erosion of road and shoulder of access road at entrance of location.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 06/23/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703143	Inspection 689703142 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831038