

Inspection Photos

Location Name: JONES 34-16 #1 & #3

API #: 05-067-07694 & 09601

INSP. #:695100646



PHOTO 1: JONES 34-16 #1 WELLHEAD



PHOTO 2: BANK BATTERY

Inspection Photos

Location Name: JONES 34-16 #1 & #3

API #: 05-067-07694 & 09601

INSP. #:695100646



PHOTO 3: JONES 34-16 #3 WELLHEAD



PHOTO 4: IMPACTED SOIL NEAR WEST SIDE OF PUMPJACK. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 6/14/19



Inspection Photos

Location Name: JONES 34-16 #1 & #3

API #: 05-067-07694 & 09601

INSP. #:695100646



PHOTO 5: IMPACTED SOIL NEAR EAST SIDE OF PUMPJACK. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 6/14/19



PHOTO 6: EROSION ON EAST SIDE OF LOCATION. Install or repair required BMPs per Rule 1002.f. CA DATE 6/14/19

Inspection Photos

Location Name: JONES 34-16 #1 & #3

API #: 05-067-07694 & 09601

INSP. #:695100646



PHOTO 7: REMOVE OR REPAIR BMP WADDLES ON EAST SIDE OF LOCATION. Install or repair required BMPs per Rule 1002.f. CA DATE 6/14/19



PHOTO 8: REMOVE OR REPAIR BMP WADDLES ON EAST SIDE OF LOCATION. Install or repair required BMPs per Rule 1002.f. CA DATE 6/14/19



Inspection Photos

Location Name: JONES 34-16 #1 & #3

API #: 05-067-07694 & 09601

INSP. #:695100646



PHOTO 9: UNUSED EQUIPMENT HOSE ON SEPARATOR SKID.
COMPLY WITH RULE 603.f. CA DATE 6/14/19

PHOTO 9: UNUSED EQUIPMENT PIPE SUB ON LOCATION
NEAR SEPARATOR HOUSE. COMPLY WITH RULE 603.f. CA
DATE 6/14/19