

Inspection Photos
Location Name: MCKENZIE FEDERAL 23-2
API #: 05-071-09564
INSP. #:695100692



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN POSTED DOES NOT DEPICT THE CURRENT OPERATOR. **COMPLY WITH RULE 210. CA DATE 7/22/19.** UNUSED EQUIPMENT UNMARKED UNUSED RISER NEAR METER HOUSE. **COMPLY WITH 603.f. & NTO REGARDING UNUSED RISERS. CA DATE 7/22/19**



Inspection Photos

Location Name: MCKENZIE FEDERAL 23-2

API #: 05-071-09564

INSP. #:695100692



PHOTO 3: IMPACTED SOIL ON WEST SIDE OF PRIME MOVER ENGINE SKID. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907" CA DATE 6/22/19



PHOTO 4: IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE COMING FROM LEAKING HYDRAULIC HOSE OR HOSE QUICK CONNECT. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907" CA DATE 6/22/19

Inspection Photos
Location Name: MCKENZIE FEDERAL 23-2
API #: 05-071-09564
INSP. #:695100692



PHOTO 5: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 6/7/19