

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

695100642

**FIELD INSPECTION FORM**

Loc ID 333881 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,	970-563-4000	maralextech@gmail.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274789	WELL	PR	12/30/2005	GW	067-08994	JAMIE LEE 33-7-9 1	PR
297401	WELL	PR	01/26/2009	GW	067-09612	JAMIE LEE 33-7-9 3B	PR

**General Comment:**

[See 5/14/19 reclamation inspection regarding removal of pit liner and cuttings on East side of location.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	PHOTO 2: TANK BATTERY/ NFPA STICKER IS FADED AND IS NOT LEGIBLE.		
Corrective Action:	Install sign to comply with Rule 210.	Date:	06/21/2019
Type	CONTAINERS		
Comment:	PHOTO 9: LABEL ON CHEM. CONTAINER NEAR WELL 33-7-9 #3B IS FADED AND NOT LEGIBLE. PHOTO 10: LABEL ON CHEM. CONTAINER NEAR WELL 33-7-9 #1 IS FADED AND NOT LEGIBLE. PHOTO 11: LABEL ON CHEM. CONTAINER NEAR METER HOUSE ON NORTHEAST EDGE OF LOCATION IS FADED AND NOT LEGIBLE.		
Corrective Action:	COMPLY WITH RULE 210.	Date:	06/21/2019
Type	CONTAINERS		
Comment:	PHOTO 12: There is a dark oily fluid in the spill prevention by the meter house.		
Corrective Action:	Comply with SB-181 and general provisions of the oil and gas act for wildlife protection.	Date:	06/21/2019

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
		Date:	<input type="text"/>

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	PHOTO 7: APPEARS TO BE RUST OR SCALE PILED NEXT TO PUMPJACK SKID ON THE 33-7-9 #3B WELL.		
Corrective Action:	REMOVE TRASH TO COMPLY WITH RULE 603.f.	Date:	06/21/2019
Type	TRASH		
Comment:	PHOTO 4: TRASH INSIDE BERM AROUND PRODUCED WATER TANK.		
Corrective Action:	REMOVE TRASH TO COMPLY WITH RULE 603.f.	Date:	06/21/2019
Type	OTHER		
Comment:	PHOTO 5: IMPACTED SOIL AROUND THE 33-7-9 #1 WELLHEAD. PHOTO 6: IMPACTED SOIL AROUND NORTH SIDE OF THE 33-7-9 #1 PUMPJACK MOTOR.		
Corrective Action:	Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907"	Date:	06/21/2019
Type	OTHER		
Comment:	PHOTO 8: IMPACTED SOIL AROUND EAST OF THE 33-7-9 #3B WELLHEAD.		
Corrective Action:	Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2), 907 & 906"	Date:	06/21/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>		corrective date
Type: Other	# 3	
Comment: CHEM. CONTAINERS		
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 2	
Comment:		
Corrective Action:		Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>		
Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 274789 Type: WELL API Number: 067-08994 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 297401 Type: WELL API Number: 067-09612 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Fail	

Comment: [stuffing boxes/rod oilers/gear boxes.](#)

Corrective Action: **Increase frequency of maintenance and self inspection schedule of equipment to prevent impacting surface materials and mixing of wastes with precipitation.**

Date: 06/21/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100673	location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831306">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831306</a>