

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2019

Submitted Date:

05/16/2019

Document Number:

695100646**FIELD INSPECTION FORM**
 Loc ID 333625 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		sabre.beebe@bpx.com	<a href="#">All Inspections</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216088	WELL	PR	01/23/1992	GW	067-07694	JONES 34-16 1	PR
297201	WELL	PR	04/18/2010	GW	067-09601	JONES 34-16 3	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 9: UNUSED EQUIPMENT HOSE ON SEPARATOR SKID. PHOTO 9: UNUSED EQUIPMENT PIPE SUB ON LOCATION NEAR SEPARATOR HOUSE.		
Corrective Action:	COMPLY WITH RULE 603.f.	Date:	06/21/2019
Type	OTHER		
Comment:	PHOTO 4: IMPACTED SOIL NEAR WEST SIDE OF PUMPJACK. PHOTO 5: IMPACTED SOIL NEAR EAST SIDE OF PUMPJACK.		
Corrective Action:	Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907"	Date:	06/21/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 2		corrective date
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Vacuum pump observed on well without COGCC approval.		
Corrective Action:	Provide COGCC with documentation showing approval of use of vacuum pump.	Date:	06/05/2019

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 216088 Type: WELL API Number: 067-07694 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 297201 Type: WELL API Number: 067-09601 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains	Fail		Fail			

Comment: PHOTO 6: EROSION ON EAST SIDE OF LOCATION UP GRADIENT FROM ROCK LINED SEDIMENT TRAP. PHOTO 7: REMOVE OR REPAIR BMP WADDLES ON EAST SIDE OF LOCATION. PHOTO 8: REMOVE OR REPAIR BMP WADDLES ON EAST SIDE OF LOCATION.

Corrective Action: Install or repair required BMPs to prevent erosion from occurring outside of BMP'S per Rule 1002.f.

Date: 06/21/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100647	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831308">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831308</a>