

Church 2
API: 05-103-05331
Inspection: 679704150



Photo 1. Pump jack looking south.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Church 2
API: 05-103-05331
Inspection: 679704150



Photo 2. Tank battery looking north.

Church 2

API: 05-103-05331

Inspection: 679704150

Fluid dripping



Photo 3. Valve leaking fluid at ~1 drop every 4 seconds.

Fluid seeping



Photo 4. Fluid seeping at bolt.

Church 2
API: 05-103-05331
Inspection: 679704150



Photo 5. Tank seam.



Photo 6. Tank berm on north side.