

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2019

Submitted Date:

05/22/2019

Document Number:

687904798**FIELD INSPECTION FORM**Loc ID 306805 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	970-563-4000	maralextech@gmail.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Hughes, Jim		jimo.hughes@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267561	WELL	PR	08/05/2003	GW	067-08800	MOLLIE CORYNNE 33-7-2 2A	PR

General Comment:

Site inspection with numbered photos at the end of this inspection report. Previous inspection document #685301373 which shows last inspected on 9/12/2016.

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted on fence at wellhead.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds and dead brush around equipment. See photo #2,3,8			
Corrective Action:	Control weeds per Rule 603.f.			Date: 06/01/2019
Type	TRASH			
Comment:	Used rags and pads around equipment. See photo #3,4,6,8			
Corrective Action:	Clean up trash and dispose of properly per Rule 603.f.			Date: 06/01/2019
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment parts sitting on concrete and plastic tub out front of fence. See photo #2,3			
Corrective Action:	Remove unused parts per Rule 603.f.			Date: 06/01/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	T-post and hogwire around pumpjack.			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 1			corrective date
Comment:	On separator stack.			
Corrective Action:				Date:
Type: Flow Line	# 7			
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from wellhead to separator that ties into offsite produced water gathering system. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-1" flowline form wellhead to pumpjack fuel gas. 1-2" flowline from separator to meter house. 1-2" flowline from meter house that ties into 1-6" flowline to offsite gathering system.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas engine.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Pumpjack gearbox seals leaking gear oil down unit and on concrete on both the east and west side of unit. See Photo #5,6,8,9		
Corrective Action:	Securely fasten fitting to ensure good mechanical condition and clean up oily waste per Rule 1002.f.(2)	Date:	06/22/2019
Type: Ancillary equipment	# 1		
Comment:	Wellhead is leaking from packing gland. See photo #7		
Corrective Action:	Repair/maintain wellhead per Rule 1002.f.(2)	Date:	05/29/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	267561	Type:	WELL	API Number:	067-08800	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing.							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention on engine oil day tank.
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402052939	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830071
687904801	MOLLY CORYNNE INSPECTION PHOTOS.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830070