

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2019

Submitted Date:

05/22/2019

Document Number:

693500140

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
317934 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_ 46290 \_\_\_\_\_  
Name of Operator: KP KAUFFMAN COMPANY INC \_\_\_\_\_  
Address: 1675 BROADWAY, STE 2800 \_\_\_\_\_  
City: \_\_\_\_\_ DENVER \_\_\_\_\_ State: \_\_\_\_\_ CO \_\_\_\_\_ Zip: \_\_\_\_\_ 80202 \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 \_\_\_\_\_ Number of Comments  
1 \_\_\_\_\_ Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections
,		dnr_cogccenforcement@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240204	WELL	SI	09/01/2017	GW	123-07992	LAURIDSON 1-A	TA

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	_____

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Walking beam and horses head laying on location		
Corrective Action:	Comply with rule 603 f	Date:	08/22/2019

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1				corrective date
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240204 Type: WELL API Number: 123-07992 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: SITE CONDITION

Comment: Well is TA. Production piping has been disconnected and bull plugged.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday May 22, 2019 at approximately 2:30PM, I, Inspector Randy Silver Conducted an on-site inspection at a KP Kauffman site Lauridson #1A, at API# 05-123-07992 in Weld County Colorado.                      While there, I observed a Well site.                      During this inspection the following possible compliance issues were observed:                      Unused equipment: Rule 603 f Corrective action date of 8-22-19 See photo 3                      At time of inspection I observed unused equipment, walking beam and horses head on location. Well is considered TA since production piping has been disconnected and bull plugged. Well has been shut in since September of 2018. Production facility #457409 that this well is tied into has been under construction since September of 2018 per inspection Doc#688500086. At time of inspection Separator on production facility appears to have all production piping removed. Inlet valves on crude oil tank are closed at time of inspection. Refer to facility inspection for further information.693500142 Doc #                      Weather conditions: over cast, road and location muddy due to storm event on previous day.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	05/22/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402052920	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830058">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830058</a>
693500141	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830049">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830049</a>