

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2019

Submitted Date:

05/30/2019

Document Number:

690003623**FIELD INSPECTION FORM**

Loc ID 336065 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285059	WELL	SI	12/01/2018	OW	123-23946	RADEMACHER 15-25	PA
297367	WELL	SI	12/01/2018	OW	123-27092	RADEMACHER 10-25	SI
297447	WELL	SI	02/01/2019	OW	123-27141	RADEMACHER 23-25	PA
297448	WELL	SI	02/01/2019	OW	123-27142	RADEMACHER 39-25	PA
297451	WELL	SI	03/01/2019	OW	123-27140	RADEMACHER 37-25	SI
297452	WELL	SI	02/01/2019	OW	123-27146	RADEMACHER 38-25	PA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared battery services at location number: 436675				
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 285059 Type: WELL API Number: 123-23946 Status: SI Insp. Status: PA

Workover

Comment: SPN 710

Corrective Action:

Date:

Facility ID: 297367 Type: WELL API Number: 123-27092 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI at well head connection to flow line.

Corrective Action:

Date:

Facility ID: 297447 Type: WELL API Number: 123-27141 Status: SI Insp. Status: PA

Facility ID: 297448 Type: WELL API Number: 123-27142 Status: SI Insp. Status: PA

Facility ID: 297451 Type: WELL API Number: 123-27140 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: Shut in at flow line connection to flow line.

Corrective Action:

Date:

Facility ID: 297452 Type: WELL API Number: 123-27146 Status: SI Insp. Status: PA

COGCC Comments

Comment	User	Date
On Thursday, May 30, 2019 at 10:03, I, Craig Carlile conducted an on-site inspection at: 336065 Operated by: Anadarko While there I observed: Large location with adjacent tankless battery, active PA operations on Radimaker 15-25 at time of inspection. Weather: Skies sun, winds calm, temp 54 F Possible compliance issues observed: None This is a summary of the inspection report.	carlilec	05/30/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003624	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835249