

Inspection Photos
Location Name: SPARROW 14-31
API #: 05-071-06832
INSP. #:695100760



PHOTO 1: WELLHEAD



**PHOTO 2: CURRENT OPERATOR NOT POSTED ON WELL SIGN.
CHANGE OPERATOR NAME TO CURRENT OPERATOR IN
ACCORDANCE WITH RULE 210. CA DATE 7/30/19**



Inspection Photos
Location Name: SPARROW 14-31
API #: 05-071-06832
INSP. #:695100760



PHOTO 3: PRODUCED WATER LEVEL IS ABOVE 2' FREEBOARD. CONTACTED JACK WISEMAN WITH EVERGREEN TO HAVE PIT DRAINED TO MAINTAIN 2' FREEBOARD. Lower fluid level so at least two feet of freeboard exists per Rule 902.b. CA DATE 5/31/19.



PHOTO 4: FREEBOARD MARKER IS INCORRECTLY INSTALLED AND IS NOT DEPICTING A 2' VERTICAL DEPTH FROM THE LOWEST PIT BERM ELEVATION. **INSTALL FREEBOARD MARKER IN ACCORDANCE WITH 902 SERIES RULES. CA DATE 5/31/19.**