

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2019

Submitted Date:

05/16/2019

Document Number:

689900683

FIELD INSPECTION FORM

Loc ID 324831 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 11 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213004	WELL	PR	02/14/2007	OW	061-06365	FRAZEE 2-6	RI

General Comment:

[Location and Stormwater Inspection.](#)

[Operator is directed to perform corrective actions outlined within this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.](#)

Location			
Lease Road:			
Type	Access		
comment:	See stormwater section. Corrective action required.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	The barrels and containers do not have labels.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 06/15/2019
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	There is various equipment and debris that is rusted and not functional. There is large rusted tanks, barrels, and various debris scattered. There is an unused cement pad. There is piles of barbed wire that is a hazard to livestock.		
Corrective Action:	Comply with Rule 603.f . Remove all unused equipment and debris.		Date: 08/15/2019
Type	UNUSED EQUIPMENT		
Comment:	There is an unknown pipe riser along the access road that is rusted with possible leakage. Lat/Long: 38.44139, -103.06295 Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f . Mark and repair or remove.		Date: 06/15/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil			
Comment:	There is oil stained soils around the well head, pumpjack, and shed. See Photos		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff.		Date: 05/20/2019
Lube Oil			
Comment:	There is barrels with what appears to be oil inside with no lid. There is barrels tipped over with oil stained soil. There are bucket lubricants near the equipment. No secondary containment. No labels. See Photos		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.		Date: 05/20/2019
Other			
Comment:	907.e. Oily Waste. There is oil stained soils around the well head, pumpjack, and shed. See Photos		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS		Date: 05/20/2019

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:	The fence around the equipment is insufficient to prevent livestock entry.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	06/15/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient	Base Insufficient	Inadequate
Comment:	The berms around the tanks are insufficient. Cattle have trampled them down.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 06/15/2019

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other	Fail	Material Handling And Spill Prevention	Fail	

Comment: There are two cattle guards along the access road that are filled in with sediment. The access road is not maintained and does not adequately drain stormwater. As a result, vehicles are traveling outside of the access road creating significant disturbance and soil compaction. There are barrels and buckets with lubricants with open lids with improper material handling and spill prevention. See Attached Photos

Corrective Action: Prevent vehicle disturbance outside of the access road and reclaim disturbance. Properly grade and install road base to allow stormwater draiange. Properly store and prevent spills. Install or repair required BMPs per Rule 1002.f.

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402046764	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825331
689900684	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825318