

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 1. Berm breach under stairs.



Photo 2. Berm breach under stairs.

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 3. Berm breach under stairs, water still in berm.



Photo 4. Water still in berm.

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 5. Spill pathway leaving location.



Photo 6. Spill pathway leaving location.

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 7. Spill pathway leaving location.



Photo 8. Spill pathway leaving location.

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 9. Spill pathway leaving location.



Photo 10. Spill pathway leaving location.

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 11. Hole in PBV tank.



Photo 12. Close up of hole in Photo 11.