

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/28/2019

Submitted Date:

05/28/2019

Document Number:

685101020**FIELD INSPECTION FORM**
 Loc ID 433035 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,		dnr_cogccengineering@state.co.us	
,		Cogcc.inspections@crestonepr.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433031	WELL	PR	04/01/2017	OW	123-37428	Maier 4B-28H	PR
433032	WELL	PR	04/01/2017	OW	123-37429	Maier 4A-28H	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds around wellhead see pic 3&4		
Corrective Action:	Comply with Rule 603.f .		Date: 06/07/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Other	WELLHEAD			
Comment:	Unknown substance in water around wellheads, water appears to be stained green see pic 1,2,3,4 &5 as comparison of other standing water on location.			
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.			Date: 05/30/2019

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	6' chain link with barb wire around all equipment		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Automation		
Corrective Action:			Date:
Type: VRT	# 2		
Comment:			
Corrective Action:			Date:

Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	200 BBLs	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with oil tanks				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	12	500 BBLs	STEEL AST		40.105170,-104.777660	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	433031	Type:	WELL	API Number:	123-37428	Status:	PR	Insp. Status:	PR
Facility ID:	433032	Type:	WELL	API Number:	123-37429	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 5/28/19 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at Crestone Peak- API -123-37428 - Maier #4b-28H in Weld County Colorado. While there, I observed Producing well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds around wellhead see pic 3&amp;4</p> <p>Comply with Rule 603.f . 6/7/19</p> <p>Unknown substance in water around wellheads, water appears to be stained green see pic 1,2,3,4 &amp;5 as comparison of other standing water on location.</p> <p>Non E&amp;P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. 5/30/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection</p>	medinaj	05/28/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402057019	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833565">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833565</a>
685101021	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833559">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833559</a>