

Inspection Photos

Location Name: SG D36 496 Pad & 8512E flowline release

Location ID: #424630 & Spill/Release ID: #464596

Inspection Date: May 30, 2019



Photo #1 – Pad sign.



Photo #2 – View of open excavation and rocky soil stockpiles from west side. Note junk pipe in foreground.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SG D36 496 Pad & 8512E flowline release

Location ID: #424630 & Spill/Release ID: #464596

Inspection Date: May 30, 2019



Photo #3 – View into excavation from west side.



Photo #4 – Additional junk pipe located northwest of excavation and soil stockpile.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SG D36 496 Pad & 8512E flowline release

Location ID: #424630 & Spill/Release ID: #464596

Inspection Date: May 30, 2019



Photo #5 – View into excavation from north side.



Photo #6 – Close up on 80 bbl produced water AST.



Inspection Photos

Location Name: SG D36 496 Pad & 8512E flowline release

Location ID: #424630 & Spill/Release ID: #464596

Inspection Date: May 30, 2019



Photo #7 – View of parted liner in NW corner of frac tank battery. Note storage of hose with metal fitting in contact with battery liner.




Photo #8 – Google Earth aerial photograph dated 10/11/2015 depicts frac tanks on location.

