

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2019

Submitted Date:

06/04/2019

Document Number:

679704335

FIELD INSPECTION FORM

Loc ID 335944 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORTH WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	
Reid, Van		van_reid@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295371	WELL	DG	05/18/2019	LO	103-11232	RNPU 197-23A1H	DG

General Comment:

[COGCC Inspection Report Summary.](#)

On 6-4-2019 at approximately 11:30, inspector Rick Moran, conducted a routine well inspection at XYO's well RNOU 197-23A1H in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report [679704335](#).

Location

Overall Good:

Signs/Marker:

	Type OTHER		
Comment:	Location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-675-4117		
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 295371 Type: WELL API Number: 103-11232 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Nabors M40 Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids

Management:

Lined Pit: YES Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: NO Disposal Location: _____

Comment: At time of inspection Schlumberger was logging the well.
24" J55 conductor set at 139'. Open hole 130' to 4312'. TD 4312'

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704336	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4840612